

कर्णाली प्रदेश सरकार

सामाजिक विकास मन्त्रालय

स्वास्थ्य सेवा निर्देशनालय

कर्णाली प्रदेश,सुर्खेत



TIME DISTRIBUTION (समय विवरण)


Date: 2080/08/11 27 November 2023 4:30 PM

Situation Overview

On the night of November 3, 2023, a 6.4 magnitude earthquake struck the Karnali Province of Jajarkot and Rukum West district, with its epicenter located in Ramidanda, Jajarkot district, at 11:47 pm. Following the initial earthquake, numerous aftershocks occurred, causing fear among the local population. The ongoing aftershocks have compelled residents to evacuate their homes and seek to stay in open areas. A total of 18 local governments are affected where Jajarkot and Rukum West are severely affected in terms of human casualties, and damage to houses in Karnali Province.



Displaced population of Nalgad ward 1, Jajarkot



Total Death	154
Total Injured	934
Total Rescued	96
Under	8
Treatment	

	District-wise Details of casualties									
	Number of Deaths					Total				
District	Under 5 Unde		er 18 Above 18		- Total		Total Injured	Rescue/Refer		
	Female	Male	Female	Male	Female	Male	Female	Male	,area	
Jajarkot	6	9	22	28	28	8	56	45	677	58
Rukum West	4	5	12	9	11	12	27	26	257	38
Grand Total	10	14	34	37	39	20	83	71	934	96

Status of Damaged Health facilities and HH				
	Damage	HH Status		
District	Health Facility	Fully Damaged	Partially Damaged	
Jajarkot	40	9,794	24,707	
Rukum West	31	9,468	13,428	
Salyan	6	151	988	
Surkhet	0	4	32	
Dailekh	0	1	5	
Kalikot	0	0	93	
Jumla	0	5	116	
Grand Total	77	19,423	39,369	

to be managed by the province and districts.

Number of Patients Under Treatment				
Bheri Hospital	Province Hospital Surkhet	TU Teaching Hospital		
3	1	4		



Psychological First Aid (PFA) for children at Bheri Municipality


Ne	Needs			
1	Continue monitoring and follow-up regarding regular essential health services.			
2	Targeted IEC materials for health awareness.			
3	Strengthening the WASH cluster in the earthquake affected area for hygiene promotion and mitigate the water			
	borne disease.			
4	Warm clothes and shelter to the people staying in open areas under the tarpaulins.			

Activation of Provincial Incident Command System/Decisions of the meetings on 2080-7-18 (6:00 AM) 1. Mapping of Human Resources (Medical and Paramedics). 2. Need assessment and gaps identification to be done and request to province from earthquake-affected districts. 3. Under the leadership of Sr. Health Education Officer Mr. Nava Raj Kandel, Public Health Administrator Mr. Bhanu Bhakta Bashyal, and Dr. Bhoj Raj Bam, PHEOC to be deployed for Information Management and dissemination from PHEOC. 4. Arrangement of ambulances and vehicle management as needed in coordination with earthquake-affected districts

Major Activities Update:

- Implementation of the Provincial Multi Hazard Contingency Plan.
- Provincial Incident Command system activated on 18th Kartik, 2080. A one-door policy was applied.
- Health and nutrition cluster meetings are conducted every day. A total of 22 cluster meeting has been conducted to date.
- 7 teams were formed and deployed to 7 affected Palikas, consisting of staff from PHSD and external development partners for situation assessment, health promotion, and preventive activities, providing psychosocial counseling, and identifying gaps and challenges.
- Need assessment of damaged health facilities and strengthening of disease surveillance reporting.
- Conduction of Health Cluster Coordination Meeting on Jajarkot EQ update with MoHP, EDCD, FWD, Curative Division, and other stakeholders.
- Meeting with the WASH cluster and the decision made to speed up water quality testing and setting up of temporary latrines/construction of toilets and distribution of health kits.
- Ongoing relief, medical management, and WASH-related activities in the affected areas by external development partners.
- A radio jingle message on mental health, hand hygiene, sanitation, diarrhea prevention, water purification, child protection, gender-based violence, possible accident, and injuries due to damaged infrastructures has been ongoing to raise post-disaster awareness for the Jajarkot and Rukum West earthquake.
- A representative from PHSD visited Jajarkot and Rukum West and had a coordination meeting with the Health Service Manager of Jajarkot and Rukum West districts regarding strengthening Active Syndromic Surveillance at the local levels and establishing two ways of communication between the local and the district level.
- A collaborative team comprising members from HSD, the Provincial Planning Commission, and UNICEF has been
 dispatched to the impacted region to enhance and restore essential health and nutrition services. The team aims to
 assess the nutritional status of children under 5 years old, pregnant women, lactating mothers, and adolescent girls.
 Additionally, they are committed to provide assistance in managing diarrhea responses in Nalgad Municipality, Jajarkot.
- A joint team from WHO, PPHL, HSD, Federal Water Supply and Sewerage Management has been deployed to Bheri, Nalgad and Aathbiskot to observe essential health service delivery and water quality surveillance.
- The team from WHO has been deployed to local level of Kushe, Nalgad, Bheri, Barekot, Junichade, Chhedagad, Shiwalaya of Jajarkot district and Aathbiskot, Chaurjahari, Sanibheri of Rukum West district to support HSD, and health coordinators of local level for active syndromic surveillance.
- The surveillance officer has coordinated with the health coordinator and visited the respective locality where the signal of possible outbreak has been detected (Kalpat, Nalgad Municipality) and facilitate in the daily reporting of collaborative syndromic surveillance.
- Help desk setup at hospitals of six affected palika (Bheri, Nalgad, Barekot, Aathbiskot, Sanibheri and Chaurjahari) for MHPSS services.







Water quality surveillance and sample collection is ongoing at community.

Earthquake Damage Health Facility List

Depart Develop Devel				<u>ige Health F</u>	acinty List		
Desired Control Free	S.N	District	Municipality	Health Facilities	Damage Status	Service Delivery Status	Needs / Support
Develop Company Company Company Company Develop Company Compan	1		Doroket	Barakat UD Limaa	The state of the s		
Record Process Proce	1		Вагекот	Barekot HP, Limsa	damaged	the hospital premises.	
Beschall Supak CHU Belliffy is contoold Not professing regions and verbox of the profession of the pro	2		Barekot	Ramidanda HP	Building is partially damaged/ Birthing center	Service provided from the HP	
Develop Control Private Column Control	-		Dorokot	Bayala CHILI	Duilding is arealized	Not providing regular conject	
Dursed Debted CP1 dos Debted 19 1	3		Вагекот	Bayala CHU	Building is cracked	Not providing regular services	Structural assessment, Repair of the cracks
Description	4		Barekot	Sirpachaur- CHU	Building is cracked	Not providing regular services	Structural assessment, Repair of the cracks
Description				D	D 311 1 1 1		0
The control to the policy of the control of the con					<u> </u>		·
Section protects protect to the PF Security of the conduction of	6		Bheri	Bahunthana HP	Building is Cracked	Service provided from the HF	
Bit Description (1997) Bit De	7		Bheri	District Hospital Jajarkot	The staff quarter building is damaged	Service provided from the HF	
Description	8		Bheri	Punma BHSC	Building is cracked	Service provided from the HF	
Book Code Net Code Book Code Book Code Net Code Book C	9			Bhuru HP	Building is cracked	Service provided from the HF	Structural assessment, Repair of the cracks
Den Marge PICORS Duckton Carded Special Control of EX. Security according to the Control of Control	10						
De la contra processe de mante la Elle Contra processe de la Contra processe de la contra de la contra pro							
Description	13						
Breat Present	14						
Description	15						
Continued Pathon IPSC Gusting in crossed Special growthed from the IP Structural assessment, Register of the continued Pathon IPSC Continued Pathon IPSC Continued Pathon IPSC P	16						
Description							
Comparison Com	19						
July							
August Salma sericu. In the lot is starting is chambaged. Kuse Acritice HP New Offer Design and Device provided from the briting. Service provided from the british. Kuse Claramaga IPP Damage in the building. Functional from the series building. Starting and Demogration of the building. Functional from the series building. Starting and Demogration of the building. Starting and Demogration of the building. Functional from the series building. Starting and Demogration of the series building. Starting and Demogration of the series building. Kuse Claramaga IPP Building is consider. Functional from the series building. Kuse Claramaga IPP Building is consider. Functional from the series building. Kuse Claramaga IPP Building is consider. Functional from the series building. Kuse Claramaga IPP Building is consider. Functional from the series building. Functional from the series buil			Chedagad		Only Birthing center building wall damaged.		
National Part	22	Jajarkot	Kuse	Samila BHSC	The Old Building is damaged	Providing service from the new building	
All Control of Part Contro					Two of the Buildings are Demage/Creeks in	Canica provided from the highing	
Kisse Gharangs IP Darrage in the building Successor Functional from the same building Substant assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural assessment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same building Struktural successment. Repear of the carried building successor Functional from the same bui	23		Kuse	Archani HP			
Authority Company Processing Processing Company Compan					,		
Riese Talegaen IPF Subting a created for the same building. Riese Calegarda IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created for functional from the same building. Riese Ohren IPF Subting a created from the same building. Riese Ohren IPF Subting a created from the same building. Riese Ohren IPF Subting a created of functional from the same building. Riese Ohren IPF Subting a created of functional from the same building. Riese Ohren IPF Subting a created of functional from the same building. Riese Ohren IPF Subting a created of functional from the same building. Riese Ohren IPF Subting Subting a created of functional from the same building. Riese Ohren IPF Subting Su	24		Kuse	Gharanga HP	Damage in the building	Functional from the same building	
Keine Knafelsbass BISC Studening scracked Functional from the same bustings Studening and Company of the cracks of the same bustings of the cracks of the crack of the cracks of the crack of the cracks of the cracks of the crack of the cracks of the crack	25		Kuse	Talegaun HP	Building is cracked	Functional from the same building	
Number P. Building is cracked Functioned from the same building Structural assessment, Repair of the cracks	26						
Name Pairs IPP Building is cracked Service Provided from the same building Subutural assessment, Repair Construction Service Provided from the IPP Subutural assessment, Repair Construction Service Provided from the IPP Subutural Assessment, Repair Construction Service Provided from the new building Subutural Assessment, Repair Construction Service Provided from the new building Subutural Assessment, Repair Construction Service Provided from the new building Subutural Assessment, Repair Construction Service Provided from the lampour service Subutural Assessment, Repair Construction Service Subutural Service Subu	27						
Name Pairs IPP Building is cracked Service Provided from the same building Subutural assessment, Repair Construction Service Provided from the IPP Subutural assessment, Repair Construction Service Provided from the IPP Subutural Assessment, Repair Construction Service Provided from the new building Subutural Assessment, Repair Construction Service Provided from the new building Subutural Assessment, Repair Construction Service Provided from the new building Subutural Assessment, Repair Construction Service Provided from the lampour service Subutural Assessment, Repair Construction Service Subutural Service Subu	29						
Nagsad Datagour IP (6) Old building partially damaged & cracks in the processory sets provided from the new building student Assessment, Repair Construction of the Suiting and Suitan Assessment, Repair Construction of the Suiting of Suitan Assessment, Repair of the cracks of Suitan Suitan Construction of Suitan Suitan Suitan Construction of Suitan Suitan Construction of Suitan Suitan Suitan Construction of Suitan Suitan Suitan Construction of Suitan Su	30						
Nagaad Aarapaan BHSC Tolet has been damaged in cracks in the building and control of the control of the building and control of the building a	31		Nalgaad	Kaina HP	Building is cracked		
Negari Fospital Negari Segri Fospital Negari Fospital			rangada	Traine Til	-		
Nalgaad Nalgaar Nalg	32		Nalgaad	Dadagaun HP (क)			
Nalgaad Natural Americans Description of the Totel. Nalgaad Laha HP Septial Constitution of the Interpretary Natural Assessment, Repair of the cracks and provided from the temporary set at publicing of the Constitution of the Building of the Septial Sep							
Nalygaad Late IP Building is considered to the temporary set up and provided from the temporary set up and provided from the semb building services and provided from the semb building should be serviced building services and semble services and semble services and semble services and semble se	33		Nalgaad	Aanapaani BHSC	l ollet has been damaged	Functional from the same building	
Nalygaad Late IP Building is considered to the temporary set up and provided from the temporary set up and provided from the semb building services and provided from the semb building should be serviced building services and semble services and semble services and semble services and semble se						Emergency, Ward & OPD services are	
Nalgaad Nalgaa	34		Nalgaad	Nagar Hospital			
Nalgaad Balgwart PB Building is cracked Functional from the same building Structural assessment, Repair of the cracks Nalgaad Balgwart PB Building is cracked Functional from the same building Structural assessment, Repair of the cracks Nalgaad Khelighurta CHU Building is cracked Functional from the same building Structural assessment, Repair of the cracks Nalgaad Khelighurta CHU Building is cracked Functional from the same building Structural assessment, Repair of the cracks Authorised					other building	Birthing center from the crack Building.	of the Building.
National Control			Nalgaad		Building is cracked	Functional from the same building	Structural assessment, Repair of the cracks
National Control	36						
Nalgad Nalgad Shuac CHU Bulding is cracked Functional from the same building Shuctural assessment, Repair of the cracks Nalgad Shuac CHU Shulding is cracked Functional from the same building Shuctural assessment, Repair of the cracks Antibiskot-11 Antibiskot-12 Antibiskot-12 Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy cracked Functional from the same building Shuctural assessment, Repair of the cracks Shuding partagy Shu	37						
Aphthisto-11 Apht	39						
Aarbbiskot-12 Aarbbiskot-12 Aarbbiskot-12 Stuckural assessment, Repair of the cracks Service provided from the same building Structural assessment, Repair of the cracks o	40			Siuna CHU		Functional from the same building	
Aarthbiskot-12 SaniBarkru BHSC Building (Rental) is damaged serviced from the temporary construction of new building serviced serviced from the temporary construction of the building serviced serviced from the same building structural assessment, Repair of the cracks from the serviced from the same building structural assessment, Repair of the cracks from the serviced from the serviced from the new building serviced from the serviced from the serviced from the new building serviced from the se							
Aarbinsko-12 Aarbinsko-12 SanBarkru BHSC Sulding preliately racked Functional from the same building Structural assessment, Repair of the cracks Aarbinsko-13 Cauban BHSC Septic tank damaged and faulting of land crud the foundation around the foundation of the foundati			Aathbiskot-11	Gatasaina BHSC	Building partially cracked		Structural assessment, Repair of the cracks
Asthbiskot-13 Sanisarkinu BHSC Bullding partially cracked Functional from the same building Structural assessment, Repair construction around the foundation aroundation around the foundation aroundation around the founda	42						
Astrbiskot-14 Soution through the foundation of Purcinitarion for same building structural assessment, Repair of the cracks of the Soution of the Building structural assessment of the Building of the November of the Building of the November of the Building of the Soution of the Building of the Buildin	42			Thulibarkhu BHSC	Building (Rental) is damaged		Construction of new building
Aathbiskol-14 Ghetma HP Old building is fully damaged and cracks in 8, old building is no montheritorial of the hours of the provided from the new building 5 and building is no montheritorial of the building of the hours of the provided from the same building 5 Baanphick Magma HP Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 160 Baanphick Magma HP Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 161 Baanphick Magma HP Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 161 Baanphick Magma HP Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 162 Chaurjahani 8HSC1 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 163 Chaurjahani 8HSC2 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 164 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 164 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in the building Functional from the same building 5 Structural assessment, Repair of the cracks 165 Chaurjahani 8HSC3 Cracks in th	42		Aathbiskot-12			set up	· ·
Aathbiskoct-14 Sankeykal UHC Bulding partially cracked Functional from the same building Structural assessment, Repair of the cracks aparphistor that Baanphistor that Basnet th	42 43 44		Aathbiskot-12 Aathbiskot-12	SaniBarkhu BHSC	Building partially cracked Septic tank damaged and faulting of land	set up Functional from the same building	Structural assessment, Repair of the cracks
Althbistot-14 Bankeyulu UHC Bulding partially cracked Functional from the same building Structural assessment, Repair of the cracks 199 Banphixot Banphixot Jhula HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 Banphixot Jhula HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 Banphixot BHSC1 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC2 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC3 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 195 BHSC4 Cracks in the building Functional from the same building Structural assessment, Re	42 43 44 45		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13	SaniBarkhu BHSC Gaubari BHSC	Building partially cracked Septic tank damaged and faulting of land around the foundation	set up Functional from the same building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair /construction
Baarphikot Baa	42 43 44 45		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13	SaniBarkhu BHSC Gaubari BHSC	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in	set up Functional from the same building Functional from the same building Service Provided from the new building	Structural assessment, Repair of the cracks Structural assessment, Repair /construction Stuctural Assessment, Repair/Construction
Baanphikot Baanphikot HP Cracks in the birthing centre Functional from the same building Structural assessment, Repair of the cracks 151 Chaurjahari BHSC1 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 152 Chaurjahari BHSC2 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 154 Chaurjahari BHSC3 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 155 Chaurjahari BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC9 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Structural assessment, Bepair of the cracks 156 Structural assessme	42 43 44 45 46 47		Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair /construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Chaurjahari BHSC1 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari BHSC2 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 154 Chaurjahari BHSC3 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC4 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC9 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC9 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC12 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari BHSC12 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks 156 Chaurjahari Chaurjah	42 43 44 45 46 47 48		Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair /construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks Structural assessment, Repair of the cracks
Chaurjahari BHSC8 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Chaurjahari BHSC12 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks September 1982 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks September 1982 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kholagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Bijayashwori HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Disparation of the same building Structural assessment, Repair of the cracks Sami Bheri-1 Chinabagar HP Building is Fully damaged Service provided from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Chinabagar HP Building is Functional from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Punctional from the s	42 43 44 45 46 47 48 49 50		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building Functional from the same building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair /construction Structural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks Structural assessment, Repair of the cracks
Chaurjahari BHSC8 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Chaurjahari BHSC12 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks September 1982 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks September 1982 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kholagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Bijayashwori HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Disparation of the same building Structural assessment, Repair of the cracks Sami Bheri-1 Chinabagar HP Building is Fully damaged Service provided from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Chinabagar HP Building is Functional from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Punctional from the s	42 43 44 45 46 47 48 49 50		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in the building Cracks in the building Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair /construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks Structural assessment, Repair of the cracks Structural assessment, Repair of the cracks
Chaurjahari BHSC8 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Chaurjahari BHSC12 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks September 1982 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks September 1982 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kholagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Bijayashwori HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Disparation of the same building Structural assessment, Repair of the cracks Sami Bheri-1 Chinabagar HP Building is Fully damaged Service provided from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Chinabagar HP Building is Functional from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Sami Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Punctional from the s	42 43 44 45 46 47 48 49 50		Aathbiskot-12 Aathbiskot-13 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Chaurjahari Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in the building Cracks in the birthing centre Cracks in the building Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Structural assessment, Repair of the cracks Chaurjahari BHSC13 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kholagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kolagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kolagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Chaurj	42 43 44 45 46 47 48 49 50		Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in the building Cracks in the birthing centre Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Structural assessment, Repair of the cracks Chaurjahari BHSC13 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kholagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kolagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Kolagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Chaurj	42 43 44 45 46 47 48 49 50 51 52 53 54	Rukum West	Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Chaurjahari Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC3 BHSC4	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in the building Cracks in the birthing centre Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Chaurjahari Kolagaun HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks (Chaurjahari Chaurjahari	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56	Rukum West	Aathbiskot-12 Aathbiskot-13 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC8 BHSC9	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in the building Cracks in the birthing centre Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Chaurjahari Sahid Smriti Nagar Hospital Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Chaurjahari Sahid Smriti Nagar Hospital Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Chaurjahari Sahid Smriti Nagar Hospital Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Chaurjahari Chaurjahari Sahid Smriti Nagar Hospital Cracks between beams and pillars Functional from the same building Structural assessment, Repair of the cracks Sani Bheri-1 Chinabagar HP Suliding is Fully damaged Functional from the temporary Sani Bheri-1 Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Simrutu HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Cracks in the building Structural assessment, Repair of the cracks Cracks in the building Structural assessment, Repair of the cracks Cracks in the building Structural Assessment, Repair of the cracks Cracks in the building Structural Assessment, Repair of the cracks Salyan	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56	Rukum West	Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC9 BHSC12	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Chaurjahari Purtimkanda HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Banphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Chaurjahari Bijayashwori HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Musikot Health Service Office Cracks between beams and pillars Functional from the same building Structural assessment, Repair of the cracks Sani Bheri-1 Chinabagar HP Building is Fully damaged Service provided from the temporary structural Assessment, Repairs/Construction Sani Bheri-1 Arma HP Solar facility damaged Functional from the same building Functional from the same building Structural assessment, Repair of the cracks Triveni Simrutu HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Functional from the same building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Provided from the same building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Structural assessment, Repair of the cracks In the building Structural assessment, Repa	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58	Rukum West	Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 Kholagaun HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Structural assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Musikot Health Service Office Cracks between beams and pillars Functional from the same building Structural assessment, Repair of the cracks Sani Bheri-1 Chinabagar HP Building is Fluly damaged Service provided from the temporary Structural Assessment, Repairs/Construction Sani Bheri-1 Arma HP Solar facility damaged Functional from the same building Structural Assessment, Repair of the cracks Sani Bheri-5 Dalli HP Cracks in Birthing Center building walls Functional from the same building Structural assessment, Repair of the cracks Triveni Simrutu HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctio	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Sani Bheri-11 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Sani Bheri-5 Dalli HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Simrutu HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Muru HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service provided from the same building Structural assessment, Repair of the cracks OPD service provided from the temporaray set up Structural assessment, Repairs/Construction OPD O	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62	Rukum West	Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC8 BHSC9 BHSC12 BHSC12 SHSC13 Kholagaun HP Kotjahari PHC Furtimkanda HP Sahid Smriti Nagar Hospital	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Sani Bheri-11 Arma HP Solar facility damaged Functional from the same building Structural assessment, Repair of the cracks Sani Bheri-5 Dalli HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Simrutu HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Muru HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service from the temporaray set up Structural assessment, Repair of the cracks OPD service provided from the same building Structural assessment, Repair of the cracks OPD service provided from the temporaray set up Structural assessment, Repairs/Construction OPD O	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62 63	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Triveni Simrutu HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Muru HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Peugha HP Cracks in the two buildings Peugha HP Structural assessment, Repair of the cracks Peugha HP Cracks in the two buildings Peugha HP Service from the temporary set up Structural assessment, Repair of the cracks Peugha HP Service from the temporary set up Structural assessment, Repair of the cracks Peugha HP Service provided from the same building Structural assessment, Repair of the cracks Structural assessment, Repair of the cracks Peugha HP Service provided from the temporary set up Service provided from the same building Structural Assessment, Repairs/Construction Peugha HP Service provided from the same building Structural Assessment, Repairs/Construction Peugha HP Service provided from the same building Structural Assessment, Repairs/Construction Peugha HP Service provided from the same building Structural Assessment, Repairs/Construction Peugha HP Service provided from the same building Structural Assessment, Repairs/Construction Peugha HP Service provided from the same building Structural assessment, Repairs/Construction Peugha HP Service provided from the same building Structural assessment, Repair of the cracks Peugha HP Service provided from the same building Structural assessment, Repair of the cracks Pugha HP Service provided from the same building Structural assess	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62 63	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-14 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Musikot	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the same building Structural assessment, Repair of the cracks Punctional from the temporary set up Structural assessment, Repair of the cracks Punctional from the temporary set up Structural Assessment, Repair of the cracks Punctional from the temporary set up Structural Assessment, Repairs/Construction Punctional from the temporary set up Structural Assessment, Repairs/Construction Punctional from the temporary set up Structural Assessment, Repairs/Construction Punctional from the temporary set up Structural Assessment, Repairs/Construction Punctional from the same building Structural Assessment, Repair of the cracks Punctional from the same building Structural Assessment, Repair of the cracks Punctional from the same building Structural Assessment, Repair of the cracks Punctional from the same building S	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62 63 64 65	Rukum West	Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Busikot Sani Bheri-1	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC4 BHSC1 BHSC12 BHSC12 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks the building Cracks between beams and pillars Building Is Fully damaged	set up Functional from the same building Service Provided from the new building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Triveni Khara HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Functional from the same building Structural assessment, Repair of the cracks Functional from the same building & Structural assessment, Repair of the cracks Functional from the same building & Structural assessment, Repair of the cracks PD service from the temporaray set up Salyan Table Salyan Table Salyan Functional from the same building & Structural assessment, Repair of the cracks PD service from the temporaray set up Service provided from the temporary structural Assessment, Repairs/Construction Service provided from the same building structural Assessment, Repairs/Construction Service provided from the same building structural Assessment, Repairs/Construction Service provided from the same building Structural Assessment, Repairs/Construction Service provided from the same building Structural Assessment, Repairs/Construction Service provided from the same building Structural Assessment, Repairs/Construction Service provided from the same building Structural Assessment, Repairs/Construction Service provided from the same building Structural Assessment, Repairs/Construction	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62 63 64 65 66 67	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-14 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Musikot Sani Bheri-11	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalii HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks between beams and pillars Building is Fully damaged Coacks in Birthing Center building walls	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Triveni Peugha HP Cracks in the building Functional from the same building Structural assessment, Repair of the cracks Darma Darmakot Birthing Center Birthing center base and wall are damaged Punctional from the same building OPD service from the temporaray set up Darma Bhalchaur HP Cracks in the two buildings Functional from the same building OPD service from the temporaray set up Functional from the same building OPD service from the temporaray set up Service provided from the temporaray set up Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporaray set up Service provided from the same building of the cracks Service provided from the same building structural Assessment, Repairs/Construction structural Assessment, Repairs/Construction punctional from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks Service provided from the same building of the cracks	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 67 62 63 64 65 66 67 68	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari	SaniBarkhu BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smritt Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks between beams and pillars Building is Fully damaged Coracks in Birthing Center building walls Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building Service provided from the temporary Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Darma Bhalchaur HP Cracks in the two buildings Functional from the temporaray set up Darma Bhalchaur HP Cracks in the two buildings Functional from the same building & OPD service from the temporaray set up Service provided from the temporary set up Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporary set up Service provided from the same building Service provided from the same building and the temporary set up. Service provided from the same building Service provided from the same building and the temporary set up. Service provided from the same building Structural Assessment, Repairs/Construction structural Assessment, Repairs/Construction building and the temporaray set up. Service provided from the same building Structural assessment, Repairs/Construction structural Assessment, Repairs/Construction building and the temporaray set up. Service provided from the same building Structural assessment, Repairs/Construction structural Assessment, Repairs/Construction structural Assessment, Repairs/Construction building and the temporaray set up.	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 67 58 60 61 62 63 64 66 66 67 68 69	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thani Bheri-11 Sani Bheri-11 Sani Bheri-11 Sani Bheri-11 Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kojahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks butween beams and pillars Building is Fully damaged Solar facility damaged Cracks in the building Cracks in the building Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Darma Bhalchaur HP Cracks in the two buildings Functional from the temporaray set up Darma Bhalchaur HP Cracks in the two buildings Functional from the same building & OPD service from the temporaray set up Service provided from the temporary set up Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporary set up Service provided from the same building Service provided from the same building and the temporary set up. Service provided from the same building Service provided from the same building and the temporary set up. Service provided from the same building Structural Assessment, Repairs/Construction structural Assessment, Repairs/Construction building and the temporaray set up. Service provided from the same building Structural assessment, Repairs/Construction structural Assessment, Repairs/Construction building and the temporaray set up. Service provided from the same building Structural assessment, Repairs/Construction structural Assessment, Repairs/Construction structural Assessment, Repairs/Construction building and the temporaray set up.	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62 63 64 65 66 67 68 69 70	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Thaurjahari Musikot Sani Bheri-11 Sani Bheri-5 Triveni Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalii HP Simrutu HP Muru HP Muru HP Khara HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in Brithing Center building walls Cracks in Birthing Center building Cracks in the building Cracks in the building Cracks in the building	set up Functional from the same building Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Darma Bhalchaur HP Cracks in the two buildings Functional from the same building & OPD service from the temporaray set up Structural assessment, Repair of the cracks Structural assessment, Repair of the cracks Service provided from the temporary structural Assessment, Repairs/Construction set up Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporary set up Service provided from the same building structural Assessment, Repairs/Construction building and the temporary set up. Service provided from the same building Structural Assessment, Repairs/Construction building and the temporary set up. Service provided from the same building Structural assessment, Repairs/Construction building and the temporary set up.	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 60 61 62 63 64 65 66 67 68 69 70	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Thaurjahari Musikot Sani Bheri-11 Sani Bheri-5 Triveni Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalii HP Simrutu HP Muru HP Muru HP Khara HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks in Brithing Center building walls Cracks in Birthing Center building Cracks in the building Cracks in the building Cracks in the building	set up Functional from the same building Service Provided from the new building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
74 Salyan Darma Darm	42 43 44 45 46 47 48 49 55 53 54 55 56 67 58 60 61 62 63 64 65 66 67 70 71	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Triveni Beri-1 Sani Bheri-1 Sani Bheri-1 Sani Bheri-1 Triveni Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks butween beams and pillars Building is Fully damaged Solar facility damaged Cracks in the building	set up Functional from the same building Service Provided from the new building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Salyan Darma Kagunohalne CHU Building (Rental) is damaged Service provided from the temporary set up structural Assessment, Repairs/Construction Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporary set up structural Assessment, Repairs/Construction building and the temporaray set up. Darma Darma BHSC Cracks in the building Functional from the same building Structural assessment, Repairs of the cracks	42 43 44 45 46 47 48 49 55 53 54 55 56 67 58 60 61 62 63 64 65 66 67 70 71	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Triveni Beri-1 Sani Bheri-1 Sani Bheri-1 Sani Bheri-1 Triveni Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks butween beams and pillars Building is Fully damaged Solar facility damaged Cracks in the building	set up Functional from the same building Service Provided from the new building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Darma Kagunohalne CHU Building (Rental) is damaged Service provided from the temporary set up Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporaray set up. Darma Darma BHSC Cracks in the building Functional from the same building Structural Assessment, Repairs/Construction Service provided from the same building and the temporaray set up. Service provided from the same building structural Assessment, Repairs/Construction Service provided from the same building and the temporaray set up.	42 43 44 45 46 47 48 49 55 53 54 55 56 67 58 60 61 62 63 64 65 66 67 70 71	Rukum West	Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Musikot Sani Bheri-11 Sani Bheri-11 Sani Bheri-11 Sani Bheri-11 Triveni Triveni Triveni Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP Peugha HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks butween beams and pillars Building is Fully damaged Solar facility damaged Cracks in the building	set up Functional from the same building Service Provided from the new building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
75 Darma Dhakadam HP Big cracks in the building Service provided from the same building and the temporaray set up. The provided from the same building and the temporaray set up. The provided from the same building and the temporaray set up. The provided from the same building structural Assessment, Repairs/Construction from the same building structural assessment, Repair of the cracks.	42 43 44 45 46 47 48 49 55 53 54 55 56 67 58 60 61 62 63 64 65 66 67 70 71		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Musikot Sani Bheri-11 Sani Bheri-11 Sani Bheri-11 Sani Bheri-11 Triveni Triveni Triveni Triveni	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP Peugha HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks butween beams and pillars Building is Fully damaged Solar facility damaged Cracks in the building	set up Functional from the same building Service Provided from the new building Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
Darma Darma Darma BISC Dracks in the building building and the temporaray set up. Darma Darma BHSC Cracks in the building Functional from the same building Structural Assessment, Repairs/Construction Structural Assessment, Repairs/Construction	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 61 62 63 64 65 66 67 68 69 70 71 72		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Triveni Triveni Triveni Triveni Triveni Triveni Darma	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP Loarmakot Birthing Center Bhalchaur HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Service Provided from the new building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
76 Darma Darma BHSC Cracks in the building Functional from the same building Structural assessment, Repair of the cracks	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 61 62 63 64 65 66 67 68 69 70 71 72		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Chaurjahari Triveni Triveni Triveni Triveni Triveni Triveni Darma	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BHSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP Loarmakot Birthing Center Bhalchaur HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural Assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
	42 43 44 45 46 47 48 49 50 51 52 53 54 55 66 57 58 60 61 62 63 64 65 66 67 71 72		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Thaurjahari Musikot Sani Bheri-11 Sani Bheri-15 Sani Bheri-11	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP Darmakot Birthing Center Bhalchaur HP Kagunohalne CHU	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building	set up Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building Functional from the temporaray set up Functional from the temporaray set up Service provided from the temporaray set up Service provided from the same	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural assessment, Repair/Construction of the Building Structural assessment, Repair of the cracks
	42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 61 62 63 64 65 66 67 68 69 70 71 72 73		Aathbiskot-12 Aathbiskot-12 Aathbiskot-13 Aathbiskot-14 Aathbiskot-14 Baanphikot Baanphikot Baanphikot Baanphikot Chaurjahari Thaurjahari Chaurjahari Thaurjahari Thaurjahari Daurjahari Dami Bheri-11 Sani Bheri-11	SaniBarkhu BHSC Gaubari BHSC Gaubari BHSC Ghetma HP Bankejyula UHC Magma HP Jhula HP Baanphikot HP BhSC1 BHSC2 BHSC3 BHSC4 BHSC8 BHSC9 BHSC12 BHSC12 BHSC12 BHSC12 BHSC12 BHSC13 Kholagaun HP Kotjahari PHC Purtimkanda HP Sahid Smriti Nagar Hospital Bijayashwori HP Health Service Office Chinabagar HP Arma HP Dalli HP Simrutu HP Muru HP Khara HP Peugha HP Darmakot Birthing Center Bhalchaur HP Kagunohalne CHU Dhakadam HP	Building partially cracked Septic tank damaged and faulting of land around the foundation Old building is fully damaged and cracks in the new building Building partially cracked Cracks in the building Cracks butween beams and pillars Building is Fully damaged Solar facility damaged Cracks in the building Birthing center base and wall are damaged Cracks in the two buildings Building (Rental) is damaged	set up Functional from the same building Service Provided from the new building & old building is non functional Functional from the same building	Structural assessment, Repair of the cracks Structural assessment, Repair/Construction Stuctural assessment, Repair of the cracks Structural assessment, Repair of the cracks

Sub-Cluster	Key Priorities Areas
	■ Need assessment and ensure access and quality of essential and emergency obstetric services.
	■ Reinforce existing functional and temporary setup birthing centers to provide skilled birth attendants and essential obstetric care to regularize ANC to PNC Care.
	Heating system and proper water supply and drainage system for temperature and hygiene maintenance.
Reproductive Health	■ Set up temporary toilets near the temporary BC.
	■ Ensure the availability of FP commodities and services to prevent unintended pregnancies (Through cap)
	■ Provide IEC materials on family planning to help individuals make informed choices about their reproductive health.
	■ Assign the dedicated staff to the affected areas to strengthen the ANC to PNC care.
	■ Continuity of routine immunization services.
Child Health and	■ Assessment of the U5 children missed during second national Vitamin A and Albendazole campaign (Kartik 17, 2080).
Nutrition Support	■ WASH awareness and hygiene kit distribution to the families having U5 children.
	■ Nutrition assessment among pregnant and lactating women, U5 children as well newborns.
	■ Provide access to prenatal vitamins and supplements, especially in populations where malnutrition is a concern.
	■ Offer individual and group counseling sessions to address the emotional stress and anxiety that dependent population may experience during and after the earthquake.
Mental Health and NCD	• Maintain confidentiality for women to express their concerns and fears related to pregnancy, childbirth, and caring for a newborn.
Neb	• Mapping the status of trained psychosocial counselor and establish health desk for psychosocial counseling through coordination with LLGs, HSO and HFs.
	■ Ensure the status of medical adherence for NCDs.
Disease Surveillance	■ Print and distribution of IEC materials for all prevalent diseases.
and Control	■ HR mobilization for regular disease surveillance and uninterrupted service delivery.
Rehabilitation	■ Need assessment of disabled population and supply of required health commodities and assistive devices.
	■To conduct rehabilitation camps with assistive devices at most affected areas





Psychosocial Counselling at Bhaunthan, Bheri Municipality

Relief materials distribution in ward no 6 of Bheri municipality

Jajarkot